

DART SERVICE INSTRUCTION


TO AMEND INSTALLATION INSTRUCTIONS D206-540 REV. K OR LATER APPROVED REVISION

REF. TCCA STC: SH94-5

REF. FAA STC: SR00386NY

It has come to Dart's attention that the D206-540-013 Heli-Utility-Basket may not sit level on some aircraft. On affected D206-540-013 Heli-Utility Baskets, the D2749-5 Strut (available from Dart Aerospace) may be installed in lieu of the shorter D2749-7 Strut as shown below.

The Heli-Utility-Basket should otherwise be installed per Installation Instructions D206-540 and maintained per Maintenance Manual Supplement MMS-D206-540. This service instruction has negligible effect on Weight and Balance.



**FIGURE 1: OPTIONAL D206-540-013 INSTALLATION
FWD CROSSTUBE SHOWN
VIEW LOOKING AFT**

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: *[Signature]*
C. PROVENCAL (DE # 03)

DATE: 18.12.14
CERT. NO.: SH94-5
ISSUE NO.: 4

APPROVED

A	NEW ISSUE, REF CAR 18-284	VS	18.12.14
REV.	DESCRIPTION	BY	DATE
DESIGN	VS	DART AEROSPACE LTD	
DRAWN	VS	HAWKESBURY, ONTARIO, CANADA	
CHECKED	WK	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9818	SHEET 1 OF 1
APPROVED	VS	TITLE	SCALE
DE APPR.	CP <i>[Signature]</i>	STRUT REPLACEMENT	NTS
DATE	18.12.14	COPRIGHT © 2018 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	